

FIG. 2




FIG. 3(a)




FIG. 3(b)




FIG. 4





FIG. 5



060433-06041
T04090 SEE 4860

FIG. 6




FIG. 7




FIG. 7

FIG. 8




FIG. 9





FIG. 10






FIG. 11

A. STENTS OVER DELIVERY SYSTEM
(NOT DEPLOYED)




FIG. 12

B. STENTS ALONE
(NOT DEPLOYED)




FIG. 13

C. STENTS EXPANDED




FIG 14

D. ONE STENT LAYOUT

- Side Access.
- BIF.

FIG 15






FIG 16








Fig. 19



09874335-060401